




## **NOTES:**

- ALL IRON GRILLES MUST BE LEVEL FROM SIDEWALK LEVEL TO APEX.
- TOP OF CONCRETE
  MOULDING CROWN
  WITH A MAXIMUM
  HEIGHT OF 3.25m FOR
  BABAN ROAD AND 2.5m
  HEIGHT REST



IRON GRILLES WITH CONCRETE MOULDING CROWN DETAILS














MAL SZ	DESIGNED BY:	PROJECT TITLE:	REQUISITIONER:	RECOMMENDING APPROVAL:	RECOMMENDING AP	ROVAL:	APPROVED BY:		SHEET CONTENTS	SHEET NO.	
THE STATE OF THE S	ARCH. JOSEPH ANDREW L. SAHIAL UNIVERSITY ARCHITECT	REPAIR OF PERIMETER FENCE AT WMSU CAMPUS A & B	PHYSICAL PLANT AND ENGINEERING SERVICES	ARCH. JOSEPH ANDREW L. SAHIAL DIRECTOR FOR PHYSICAL PLANT & ENGINEERING SERVICES	VI	. MADROÑAL, DPA DE PRESIDENT TRATION AND FINANCE	MA. CARLA A. OCHOT URIVERSITY PR	TORENA, RN, PhD RESIDENT		A2 02 06/	CERTIFICATION INTERNATIONAL ISO 90012015
AND ANG A CHY	PRC: 0010557 PTR: 2792209 TIN: 445-013-228	LOCATION: WMSU LOT-A&B, BARANGAY BALIWASAN, ZC		PRC: 0010557 PTR: 2792209 TIN: 445-013-228		\/			C. VALDEZ		











REQUISITIONER: RECOMMENDING AP DESIGNED BY: PROJECT TITLE: RECOMMENDING APPROVAL: PPROVED BY: SHEET CONTENT SHEET NO MA. CARLA A. OCHOTORENA, RN, PhD
UNIVERSITY PRESIDENT ENGR. AHWEDZAM S NASALUDIIN, MS STE.
TECHNICAL ASSOCIATE FOR INFRASTRUCTURE  $\widehat{S2}$ REPAIR OF PERIMETER FENCE ARCH. JOSEPH ANDREW L. SAHIAL JOSELITO D. MADROÑAL, DPA PHYSICAL PLANT AND VAB AT WMSU CAMPUS A & B DIRECTOR FOR PHYSICAL PLANT & ENGINEERING SERVICES VICE PRESIDENT FOR ADMINISTRATION AND FINANCE 06 06 **ENGINEERING SERVICES** REAGAN S. ABANTO TIN: 94972247 PRC: 0010557 PTR: 2792209 TIN: 445-013-228 PRC: 0149752 LOCATION: WMSU LOT-A&B, BARANGAY BALIWASAN, Z